

**Town of Waterville Valley
Hurricane Irene
Aftermath Photo Log**

Prepared by: Christopher Hodges, Director of Public Safety

Photo	Photo Description
 A photograph of a concrete dam with water cascading over its spillways. The dam is situated in a wooded area with a rocky stream bed in the foreground. A road with a white railing is visible on the left side of the dam.	<p>Corcoran's Pond Dam Taken on 08/29/11</p>
 A photograph of a small wooden foot bridge crossing a stream. The bridge is partially obscured by two large, rusted metal pipes that have been laid across the stream bed. The surrounding area is a dense forest.	<p>Foot Bridge located behind the Snowy Owl Inn</p>
 A photograph showing a grey metal pump house with significant erosion at its base. The ground in front of the building is a mix of dirt and rocks, with a deep channel of water or mud running alongside it.	<p>Pump House #1 Erosion Taken on 08/29/11</p>

**Town of Waterville Valley
Hurricane Irene
Aftermath Photo Log**

Prepared by: Christopher Hodges, Director of Public Safety



Corcoran's Pond Sediment & Debris
Taken on 08/29/11





Corcoran's Pond Sediment & Debris over the banks.
Taken on 08/29/11



Nordic Trail Damage (Sample)
Taken on 08/29/11



**Town of Waterville Valley
Hurricane Irene
Aftermath Photo Log**

Prepared by: Christopher Hodges, Director of Public Safety

	<p>Boulder Path Road, along the Mad River. Taken on 08/30/11</p>
	<p>Boulder Path Road, along the Mad River. Taken on 08/30/11</p>
	<p>Mad River and final location of the Nordic Trail Bridge. Approximately 1122' downstream from original location. Taken on 08/30/11</p>

**Town of Waterville Valley
Hurricane Irene
Aftermath Photo Log**

Prepared by: Christopher Hodges, Director of Public Safety

	<p>Nordic Trail Bridge abutments at original location of the bridge on the Mad River. Taken: 08/30/11</p>
	<p>Tripoli Road looking South from the intersection of West Branch Road. Taken: 08/31/11</p>
	<p>West Branch Road Bridge. Debris caught under bridge. Taken: 08/29/11</p>


**Town of Waterville Valley
Hurricane Irene
Aftermath Photo Log**

Prepared by: Christopher Hodges, Director of Public Safety

	<p>West Branch Road Bridge, Debris and utility damage on bridge. Taken: 08/29/11</p>
	<p>West Branch Road Bridge, Debris and utility damage on and around bridge. Taken: 08/29/11</p>
	<p>Embankment and property erosion behind Tyler Spring Condominium. (Mad River) Taken: 08/30/11</p>

**Town of Waterville Valley
Hurricane Irene
Aftermath Photo Log**

Prepared by: Christopher Hodges, Director of Public Safety

	<p>Route 49 Traffic Measures –S-Curve Washout #1 (North) Taken: 08/31/11</p>
	<p>Route 49 Traffic Measures –S-Curve Washout #2 (Middle) Taken: 08/31/11</p>
	<p>Route 49 Traffic Measures –S-Curve Washout #3 (South) Taken: 08/31/11</p>